Local Authority	Spoil Tips/Tip Grouping Name	Spoil Tips/Tip Grouping Ref	Risk Rating	Ownership	Description of works	How works were identfied	Predicted Spend 2021/22
NPTCBC	Complexe at Centre of Cwmafan	A01	C	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	
NPTCBC	Dyffryn Rhondda Colliery Riverside	A02	B	Local Authority	Reconstruction of gabion wall	Coal Authority inspection	750,000
NPTCBC	Nantewlaeth, Cymmer	A06	B	Local Authority	Scour protection	Coal Authority inspection	
NPTCBC	Old Dyffryn Rhondda Aerial Tips	A08	B	Local Authority	Reprofile minor slip areas & clear drainage. Fencing to prevent animal access.	Coal Authority inspection	100,000
NPTCBC	Ynys Y Gwas Tips, Cwmafan	A21	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	55,000
NPTCBC	Torymynydd Rhondda Colliery, Pwll Y Gwlaw, Cwmafan	A25	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	8,000
NPTCBC	Bryn (Navigation), Port Talbot	A27	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	1,800
NPTCBC	Pwll Y Gwlaw, Cwmafan	A37	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	7,000
NPTCBC	Abergwynfi School, Culvert	A41	B	Local Authority	Fencing	Coal Authority inspection	5,000
NPTCBC	Darren Tips, Trebanos	L04	B	Local Authority	Fencing, vegetation clearance & drainage	Coal Authority inspection	3,100
NPTCBC	Old Tarrini, Gleisions mine	L8, L16, L19	B	Local Authority	Minor erosion, fencing, vegetation clearance & drainage	Coal Authority inspection	44,500
NPTCBC	Cwmgors	L69	B	Local Authority	Prevent vehicular access, vegetation clearance & drainage	Coal Authority inspection	20,200
NPTCBC	Pontwallby, Glynneath	N22	B	Local Authority	Drainage work	Coal Authority inspection	94,150
NPTCBC	Cilmaengwyn	L44	D	Local Authority	Consultants Hazard Assessment		28,000
					Design & Site Supervision costs		40,493
					Tip remapping		67,123
							1,157,243