

Local Authority	Spoil Tips/Tip Grouping Name	Spoil Tips/Tip Grouping Ref	Risk Rating	Ownership	Description of works	How works were identified	Local Authority Spend 2020/21
NPTCBC	Complexes at Centre of Cwmafan	A01	C	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	£14,205.11
NPTCBC	Dyffryn Rhondda Colliery Riverside	A02	B	Local Authority	Reconstruction of gabion wall	Coal Authority inspection	£8,357.00
NPTCBC	Old Dyffryn Rhondda Aerial Tips	A08	B	Local Authority	Reprofile minor slip areas & clear drainage. Fencing to prevent animal access.	Coal Authority inspection	£26,208.53
NPTCBC	Bryn (Navigation), Port Talbot	A27	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	£12,000.00
NPTCBC	Pontwallby, Glynneath	N22	B	Local Authority	Vegetation clearance & drainage	Coal Authority inspection	£17,595.59
NPTCBC	Cilmaengwyn	L44	D	Local Authority	Consultants Hazard Assessment Design & Site Supervision costs Tip remapping		£62,100.53 £18,188.17 £30,835.27
TOTAL							£189,490.20